



**PHOTO 1:** 7/13/2021 – Front of Home Looking West.



**PHOTO 2:** 7/13/2021 – Interior Diagonal Cracking and Efflorescence at Wall Step.





**PHOTO 3:** 7/13/2021 – Interior Vertical Basement Wall Crack.




**PHOTO 4:** 7/13/2021 – Interior Vertical Crack in Garage Foundation Wall.






**PHOTO 5:** 7/13/2021 – Interior Settlement Crack in Garage Foundation Wall.



**PHOTO 6:** 7/13/2021 – Exterior Map Cracking along West Garage Wall.





**PHOTO 7:** 7/13/2021 – Exterior Map Cracking along West Garage Wall.